



Technical Journal

TITLE:

Protective caps for wheel screws, falling off

REF NO: TJ 32163.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-03-21	STATUS DATE: 2017-03-21
FUNC GROUP: 7716	FUNC DESC: wheel nut	Page 1 of 5	

“Right first time in Time”

Attachment

File Name	File Size
TJ 32163 - 1.jpg	0.2238 MB
TJ 32163 - 2.jpg	0.1206 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2015-2016		0189726-0200260	201448-201614
134							2015-2017		0354644-0438961	201448-201708
135							2015-2016		0327632-0377263	201448-201616
136							2015-2016		0218202-0274097	201448-201619
137							2016-2017		0000001-0004710	201524-201708
155							2015-2017		0250900-0367116	201448-201708
156							2015-2016		0702450-0928332	201448-201616
156							2017-2017		0000001-0144277	201617-201708
157							2015-2017		0000001-0038896	201450-201708



Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		0000001-0017618	201617-201708
235							2017-2017		0000001-0018401	201624-201708
236							2017-2017		0000001-0005120	201646-201708
256							2016-2017		0000001-0174565	201505-201708

CSC Customer Symptom Codes

Code	Description
U4	Tires/Other tire problems
X4	Wheel rim, wheel bolts/Broken

VST Operation Number

VST Operation Number	Description
99400-2	General reimbursement acc. to TJ/QB

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

If protective caps over wheel screws are missing / falling off (refer to example [TJ 32163 - 1.jpg](#)) then follow advice under Service.

New protective caps in silver and dark grey colors has been introduced from 2017 week 09 that are snapped on over the wheel screw flange, see [TJ 32163 - 2.jpg](#)

SERVICE:

If protective caps are missing and the vehicle is within the chassis number range in TJ header, then remove all remaining caps and install new protective caps on all wheel screws.

Note: Also replace the protective caps for the 4 lockable wheel screws if car is equipped with this accessory.

New parts:

Silver (VDN code 6F03): kit 20 pcs P/N 31660917, kit 4 pcs for lockable screw P/N 31650000

Dark grey (VDN code 6F01): kit 20 pcs P/N 31660916, kit 4 pcs for lockable screw P/N 31650002

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 7716.

To view TJ attachment continue to next page. This TJ has two attachments.



TJ 32163





TJ 32163

