



Parts Bulletin

TITLE:

**Recall R89712: Airbag Inflator
Model Year 2017 S60, V60, S60CC, V60CC, XC60**

**GROUP:
88**

**CAT/NO:
R89712**

**REFERENCE BULLETINS:
QB: R89712, TJ: 32261**

**CAR MARKET:
United States and Canada**

COPY TO / CIRCULATIONS (PLEASE INITIAL):

**ISSUE DATE:
2017-01-12**

**STATUS DATE:
2017-01-12**

**GENERAL
MANAGER**

**PARTS
MANAGER**

**SERVICE
MANAGER**

**SALES
MANAGER**

Page 1 of 2

“Right first time in Time”

Reference Bulletins: QB R89712, TJ 32261

PLEASE NOTE FOLLOWING CHANGES:

QUANTITY CHANGE TO PART 985846 AND NEW PART 95722 (CLAMP) ADDED

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R89712 on certain model year 2017 S60, V60, S60CC, V60CC, XC60 vehicles.

The affected vehicles may have been equipped with front passenger and/or front seat side airbag inflators that do not meet specifications, and fail to deploy properly in the event of a crash. This could increase the risk of injury to the occupants.

The corrective action is to replace the affected front passenger and/or front seat side airbag modules.

A total of 376 U.S. and 96 Canadian vehicles are eligible for this recall.

The following part numbers apply:

Part Number	Description	Qty
30715603	Front Passenger Airbag	1
31418253	Driver's Front Seat Side Airbag	1
31418254	Passenger Front Seat Side Airbag	1
31418256	Driver's Front Seat Side Airbag	1
31418255	Passenger Front Seat Side Airbag	1
985846	Nut	6*
95722	Clamp	48**

* Used with seat airbag replacement (3 nuts per seat)

** Used with seat airbag replacement, maximum 24 clamps per seat

Parts Bulletin 88-R89712



Retailers will need to access the eligible vehicle list in the Retailer letter or in TIE to determine which airbag(s) will need to be replaced for each individual VIN. Please refer to the referenced information for instructions.

NOTE: Airbags in Canada are not returnable. Airbags in the US may be returnable under the Supplemental Restraint Return Procedures.