



Technical Journal

TITLE:

Squealing noise from rear brakes at low speedREF NO:
TJ 31007.8.2ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-01-13STATUS DATE:
2017-01-24FUNC GROUP:
5122FUNC DESC:
Brake drum; brake disc

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2017		0000561-0124123	201505-201626

CSC Customer Symptom Codes

Code	Description
1P	Brakes/Unusual noise/Rear

VST Operation Number

VST Operation Number	Description
51221-3	Brake pads rear replacement (only for chassis number below 22196)
51216-0	Brake discs rear 2x replacement

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text



DESCRIPTION:

VIDA= Vehicle Information and Diagnostics for Aftersales

If symptom of squealing noise occur from the rear brakes during braking (mainly at low speeds), then follow the advice under Service.

A new brake disk with changed material was introduced from chassis number 124124.

* brake grease part number added

SERVICE:

* For chassis numbers below 22196:

- replace rear brake discs and rear brake pads according to VIDA.

* For chassis numbers between 22196 and 124124:

- replace only the rear brake disc according to VIDA.

* Parts: Refer to VIDA.

Please use Volvo part# 31400019 on locations specified as per VIDA instructions for grease applied to caliper bracket mounting locations.

VEHICLE REPORT:

* Yes, if the new brake disc is already installed (can be identified with part number 31471815), then submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 5122.

* Please include a video or sound recording of the noise, include speed, weather conditions and other observations in the vehicle report.