



Technical Journal

TITLE:
XC90 PHEV Turtle in DIM, DTC ECM-U005500

REF NO: TJ 32338.4.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-04-28	STATUS DATE: 2017-05-03
FUNC GROUP: 2621	FUNC DESC: Coolant pump, complete	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-2017		-	201526-201716

CSC Customer Symptom Codes

Code	Description
AJ	Driving/Poor performance/lacks power

VST Operation Number

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ECM	U005500	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

* Changed week for release of new software to 2017w20.
If ECM-U005500 is set, follow advise under "Service".

SERVICE:

*Critical cases can be updated via remote.
Do not replace any parts as this is identified as a software issue.

VEHICLE REPORT:

No more reports needed just for case building.