



Team Tips

ARTICLE: I-17-01-01

DATE: 01/24/2017

Published for Indian Motorcycle Dealerships, Distributors, and Service Technicians

SUBJECT: Indian Scout – Transmission Service Parts Information**MODELS: 2015-2016 Indian Scout 1200 Models****NOTE: Scout Sixty models are not affected by this change.**

Indian Motorcycle has implemented an update to the Scout 1200 transmission assembly which will affect how service parts can be ordered for 2015 - 2016 models. Reference the TRANSMISSION IDENTIFICATION section below to understand the identifying mark used to distinguish the new transmission from the old.

The updated transmission assembly is functionally the same as the original transmission, however, individual components (gears, washers, bushings, input shaft, output shaft) **are not interchangeable**. Using original transmission parts in conjunction with new may result in severe transmission damage.

PARTS INFORMATION: Indian Motorcycle is no longer able to offer individual transmission components as service parts for 2015 - 2016 Indian Scout 1200 motorcycles. In the event that any transmission parts require replacement, they will now be sold as a Service Kit ONLY. Affected service parts from the original transmission will automatically supersede to the new transmission kit (PN: 2206256)

TRANSMISSION IDENTIFICATION: The end of the new output shaft assembly has a stamped “Dot” ① as shown below. The “Dot” indicates components of transmission can be replaced and kit replacement is not required.

