



SI B33 02 16
Rear Axle

March 2016
Technical Service

Howling Noise from the Rear Differential

MODEL

F30 (3 Series Sedan) PHEV

SITUATION

When coasting from 85 – 70 mph, there is a howling noise from the rear differential.

CAUSE

Resonance behavior during the running-in phase of the PHEV rear differential

PROCEDURE

Do not replace any parts. Inform the customer that this running-in phase can take up to 700 miles.

WARRANTY INFORMATION

Not Applicable.

[Copyright ©2016 BMW of North America, Inc.]