

9003585 11/29/2017 MY12 - 16 D2, DJ, DD, DP MY16 DF

GPOP - Issue Review System

Part Number: 68210071A\$, 05187880A\$

Part Description: Intake Grid Heater
Grid Heater Relay

Issue Description: 2012 - 2016 6.7L Cummins engines with Intake Heater issues or DTC P2609 and P0542, please replace the Intake Heater Grid and Relay as a set. 68210071A\$ (heater grid) and 05187880A\$ (relay). Inspect electrical cable between the heater grid and relay for signs of possible overheating. Replace cable as necessary. ~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
