

9003675 03/08/2017 MY17 RU

GPOP - Issue Review System

Part Number: 82215177A\$, 68330446A\$, 68330444A\$

Part Description: Overhead DVD Player

Issue Description: Before replacing the overhead DVD player for an inoperative condition, check the 14 pin connector at the DVD player for loose or pushed out pins. If the connection is ok then proceed with the repair.

Before replacing the DVD player for a scratched or distorted screen make sure the plastic protective film is removed. ~

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.