

9003750 06/28/2017 MY17 RU

GPOP - Issue Review System

Part Number: 5VM63DX9A\$, 5VM63PD2A\$, 5SP35DX9A\$, 5SP35PD2A\$

Part Description: Quarter Panel Assembly

Issue Description: If customer complains of warped or gapped vacuum swing door, please ensure both high retention clips have been fully seated. If not, please reinstall the part and verify engagement of the high retention clips to see if gap/warp issue is resolved prior to replacing the part.

~_____~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
