

GPOP - Issue Review System

Part Number: 68395010A\$, 68234994A\$

Part Description: Transfercase Seal, Transmission Output Seal

Issue Description: If vehicle has a fluid leak between the transfer case and the transmission on a 2017 AWD Charger/300/Challenger and it has been determined that the transfer case is leaking, the vehicle can be repaired by:

Transfer Case replace -
68214750AC 3.6 Pentastar
68214751AC 5.7 Hemi

Replace Front Case Half -
68101734AA 3.6 Pentastar
68101737AA 5.7 Hemi

Note: The transfer case oil already has dye in it so leak confirmation with a black light can be achieved.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.