

9003765

08/16/2017

MY17

MP

GPOP - Issue Review System

Part Number: 55112669A\$, 68350809A\$

Part Description: Washer Fluid Sensor

Issue Description: When the washer fluid light indicates low fluid after filling the reservoir, check the washer sensor wire harness for cuts / damage, check pin for looseness. Monitor fluid level sensor light while doing connector wiggle test and if necessary disconnect and reconnect connector.

If it is necessary to replace the washer fluid sensor, please be careful to perform repair without damaging sensor.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
