

9003704 10/18/2017 MY14 – 17 DS, LD, WD, WK MY15, 16 LA MY14 LC MY14 – 16 LX

GPOP - Issue Review System

Part Number: 68261504A\$, 68233701A\$, 68227208A\$, 68227207A\$, 52014750A\$

Part Description: Trans Oil Pan, Heater Tube or O-ring, Heater

Issue Description: Applies to vehicles equipped with 8 speed transmissions only; If you have a leak that appears to be at the pan the use of proper leak detection is recommended. The fluid in the 8 speeds can be detected with a black light and there are aftermarket spray on leak detection materials to help ensure that the leak is properly diagnosed and not from another location such as cooler lines, heater tubes, or case porosity.

If you have a leak concern please note that the transmission pan gasket is available for many of the 8 speed applications FCA offers. See your parts specialist for the proper gasket for the repair.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~
