



Technical Journal

TITLE:
P5-XC60 Front License plate installation

REF NO: TJ 32942.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-07-27	STATUS DATE: 2017-07-31
FUNC GROUP: 8611	FUNC DESC: Bumper, front	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
Location.jpg	0.0714 MB
XC60 License plate.jpg	0.0841 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246							2018-2018		0000001-0999999	201717-999952

CSC Customer Symptom Codes

Code	Description
ZW	Exterior/Component exterior wrong installation/missing

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

Installation of front license plate H-frame.

SERVICE:

Attach H-frame to the front bumper (see attached pictures for reference) using Screw kit: 30632653 (supplied with vehicle).

Note: Insert the screws in the same location as shown.

VEHICLE REPORT:

When submitting a Vehicle Report for a condition described in this TJ, use concern area "Vehicle Report and sub concern area "Support Not Needed" with function group 8611.

To view TJ attachments continue to next page. This TJ has two attachments.

