

SSM
46400

2011-2015 Explorer and MKT vehicles requiring replacement of right front axle shaft no longer require installation of the center support bearing heat shield(7F469). The heat shield can be discarded.