

SERVICE ADVISORY # 17-280**Hideout Bedroom Furnace Vent**

It has been determined some 2017 Hideout 308BHDS and 281DBS models were built without the 4 inch rotaire vent installed in the bedroom wall. This service advisory explains how to correct the situation.

Models Included:	2017 Hideout 308BHDS and 281DBS
Serial Number Range:	H7208819 - H7208938
Parts Required:	(1) KRV # 399411 Grill - Vent Cover - 2" - Rotovent - Black
Tools Required:	- 4" Hole Saw - Tape Measure - Screw Gun with #2 Square Bit - Portable Vacuum Cleaner

Note – Check serial number on Key Express to verify the campaign is open. Some vehicles were repaired before they left Keystone.

REPAIR INSTRUCTIONS**Step 1**

Locate the trailer on a level, flat, hard surface. Chock the wheels.

Step 2

Locate the access panel behind the bathroom vanity cabinet door and remove the 2 screws holding the bottom access panel, Figure 1, to find the 2 inch ducting as shown in Figure 2.

**Step 3**

From the outside of the bathroom wall, drill a 4" hole, 6" up from the floor and centered in the wall through the inner and outer panel, Figure 3.

Step 4

Clean saw dust and debris with vacuum.



Step 5

Pass the heat duct through the hole and fasten the rotary vent to the duct. Use 2 screws to attach the duct to the vent, Figure 4. Install complete vent to wall and press rotary vent into place, Figure 5.

**Step 6**

Reinstall panel in bathroom lavatory cabinet.

WARRANTY REIMBURSEMENT

Submit the claim on Key Express using **Flat Rate Code # 7128042A** with **Service Advisory # 17-280** noted in the customer complaint section of the form. The amount of time authorized for this repair is .5 hours.

Please call Keystone RV Customer Service at **(866) 273-1454** if you have any questions.