



Service Bulletin

File in Section: -


Bulletin No.: 16-NA-160

Date: May, 2016


INFORMATION

Subject: Wet Residue or Staining on Bottom of Brake Calipers


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze (VIN B)	2016	2016			All	All

Involved Region or Country	North America
Condition	 <p style="text-align: right; font-size: small;">4516129</p> <p>Some customers/technicians may discover some wet residue or staining on bottom of brake calipers.</p>
Cause	This may be caused by excess assembly lubricant seeping out of the brake piston dust boot.

Correction



4516132



4516134

This residue has no effect on brake operation. No repair is needed. Do not replace the caliper for this condition.

Version	1
Modified	

