

[Next Unread Message](#)

View Message

Sent on	01	16	2018	Expires on	02	16	2018
From	Parts and Service Division						
Subject	17M NSX Wind Noise Concern						

PRIORITY/ACTION REQUIRED

To: All Acura Parts and Service Managers, Advisors, and Personnel
From: American Honda Parts, Service, and Technical Division
RE: 17M NSX Wind Noise Concern

Print this *iN* message and provide a copy to the Service Manager, Service Advisors, and appropriate personnel.

Dear Service Manager,

American Honda is reviewing a new countermeasure for a wind noise coming from the side window in the NSX. If you receive a NSX with VIN# ending in 926 or less, with the client complaining about a wind noise heard when driving over 50 mph, and you are able to verify the noise is coming from the area where the side power mirrors are (either side); please report it to TechLine immediately before conducting any repair. TechLine will provide further instructions on how to address this issue in details.

Thank you.