



Preliminary Information

PIT5607 Service Engine Soon MIL on P050F Stored

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Terrain	2018	All	All	All	All
Chevrolet	Equinox	2018	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		None				
Condition:		Intermittent SES MIL On , DTC P050F Stored				
Cause:		Engineering is investigating this concern.				

Correction:

Engineering is currently investigating this concern.

Service Procedure:

Test the brake vacuum system to verify no leaks present and verify brake operation performance. If leak identified follow SI diagnostics. If no leak identified clear codes. GM is investigating root cause for DTC setting with no system leak present.

Warranty Information

Labor Operation:	Description:	Labor Time:
2480358	Inspect For Vacuum Leak and Clear DTC's	0.3

Version History

Version	
	1

