

"DOCUMENT UNCONTROLLED IF PRINTED"

DOC #	PROCESS NAME	PAGE	REVISION	STATION	BY	DATE
AR852	MorRyde Suspension Repair	1 OF 1		SER-G	BHERSH	1/9/2018

Read process before beginning. If you do not understand any part please contact: Chris Ward, VP of Parts and Warranty at 1-866-953-5555 or by E-mail @ cward@ARBOCSV.com.

Good Mechanics safety practice must be followed on any repairs.

Safety practices should include but not be limited to properly supporting the chassis, axles, blocking tires, and a work area free of clutter.

Complaint: Mor/Ryde rear suspension raises concerns with step height at ramp. Lifts vehicle approx. 3 inches.

Cause: Design and installation of Mor/Ryde suspension.

Correction: Replace front hanger bracket and remove Mor/Ryde rear suspension to reinstall OEM spring.

Vehicles Affected: City of Charlotte SOI-F buses 3045-3063

Labor Operation Code: 0114601

Authorization Required

Labor Time Allowance: 1.5 hours

Parts Returned: No

Tools Required

Parts Required

- 2 1310707 Front Lowered SOI-F Spring Hanger Mount
- 2 2005262 Front/Rear Leaf Spring, Ford Chassis, Shackle

