



Preliminary Information

PIP5465A Diagnostic Tip - Exhaust Heat Exchanger Coolant Leak

Models


Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2016 - 2018	All	All	1.8L LKN	All
Involved Region or Country	North America					
Additional Options (RPO)	(1.8L) LKN					
Condition	Smoke from exhaust system, coolant loss.					

Correction:

When Pressure testing the coolant system to isolate a coolant loss concern, remove the Exhaust front pipe assembly (2) from the Exhaust Heat Exchanger assembly (1) and check it for signs of internal coolant leakage.

If an internal leak is found in the Exhaust Heat Exchanger, replace and retest for system leakage.

Exhaust Heat Exchanger shown below (#1)



Version History

Version	
2	02/05/2018 Updated to add 2018 model year.

