

Subject		Market	
Harman Map Update Request Code		USA	
Service Category	Section		
Audio/Visual/Telematics	Navigation/Multi Info Display		
Applicability			
Multiple Scion Models			

APPLICABLE VEHICLES

2016	FR-S	2016	tC
2016	iM		

CONDITION

Some vehicles may display a 22-digit request code when attempting to perform a navigation map update.

RECOMMENDATIONS

TIS currently allows for the input of a 16-digit request code.

Development is currently underway to support 22-digit request codes, however at this time it is not possible to update map data in these models/model years.

LINK REFERENCES

This Tech Tip does not contain any link references