

QUARANTINE NOTICE

Reference number:	QN-01-1029	Issued: 15 February, 2018
Subject:	Replace Bonnet Meshes with Bonnet Blades	
Model(s):	DB11	
VIN Range:	Refer to the attached list of Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Note: *This repair is the same as Service Action SA-01-1029. Use this Quarantine Notice for vehicles that are not registered and have not been given to a Customer.*

Some vehicles in the affected VIN list for this Quarantine Notice may now be registered and given to a Customer. Make sure that you do a check of the Online Dealer Warranty (ODW) database to make sure that all necessary work is done to every vehicle.

Reason for this Quarantine Notice

Aston Martin has found that some DB11 vehicles had bonnet meshes installed in error. Do the procedure that follows to install the correct black bonnet blades on all applicable vehicles.

Workshop Procedure

This workshop procedure has the parts that follow:

- Part A – Remove the bonnet meshes
- Part B – Install the bonnet blade and mesh assemblies

Note: *The images in part A of the procedure that follows show the left side bonnet mesh removal. The same procedure is applicable for the right side bonnet mesh removal.*

Part A – Remove the bonnet meshes.

1. Open the bonnet

2. Remove the eight push clips that attach the left-side centre wheel-arch liner to the bonnet (refer to Figure 1).




Figure 1

3. Release the left-side centre wheel-arch liner from the bonnet (refer to Figure 2).




Figure 2

4. Remove the left-side centre wheel-arch liner from the bonnet (refer to Figure 3).




Figure 3

5. Remove the six nuts that attach the left-side outboard bonnet mesh to the bonnet (refer to Figure 4).




Figure 4

6. Remove the left-side outboard bonnet mesh from the bonnet (refer to Figure 5).




Figure 5

7. Do steps 2 thru 6 again to remove the right side bonnet mesh.

Part B – Install the new bonnet blade and mesh assemblies

8. Install the new bonnet blade and mesh assemblies (refer to Workshop Manual procedure 01.08.BN).

Parts Data

Description	Part Number	Quantity
BONNET VENT BLADE BLACK RIGHT SIDE	HY53-16A856-BB	1
BONNET VENT BLADE BLACK LEFT SIDE	HY53-16A857-BB	1
BONNET VENT OUTBOARD DEEP RIGHT SIDE BLACK	HY53-16C690-AA	1
BONNET VENT OUTBOARD DEEP LEFT SIDE BLACK	HY53-16C691-AA	1
M6 LOCKNUT FLANGE NY	703164	12
NUT M5 HEX FLG PLAS	703165	6

Warranty Data

Procedure and Labour Time

Description	Labour Time
Replace Bonnet Meshes with Bonnet Blades.	0.40 hours

If you have any questions related to this Quarantine Notice, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™.