

MODEL: Karma Revero

DATE: February 2018

TITLE: Oil and Filter Change Campaign

Revised Release 2.5.18

PRIORITY: As Indicated

APPLICABILITY: MY17-MY18 Karma Revero

MARKET REGION: North America

PURPOSE: Oil and Filter Change

Certain Karma Revero vehicles may have been over filled with oil during production which could result in a false misfire condition.

Karma Automotive has issued this customer satisfaction campaign to address the potential for this to occur. Complete the following procedure for all involved vehicles.

1. Follow the standard oil and filter change procedure (Oil- Drain and Refill) in the service manual found on the dealer portal. No more than 5 qts should be added when changing oil and filter.
2. The “remaining oil life” should be reset to 100% on the touch panel interface when complete.

Go to:

“My Karma” > Settings > Vehicle > Oil Life Reset



“My Karma”



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.



Service Campaign

CC-18-12-01

MODEL: Karma Revero

DATE: February 2018

TITLE: Oil and Filter Change Campaign

Revised Release 2.5.18

Affected Vehicles:

50GK41SA1HA000011	50GK41SA2JA000024	
50GK41SA7HA000014	50GK41SA4JA000025	
50GK41SA5HA000013	50GK41SA6JA000026	
50GK41SA9HA000015	50GK41SA9JA000019	
50GK41SA0HA000016	50GK41SA5JA000020	
50GK41SA2HA000017	50GK41SA8JA000027	
50GK41SA4HA000018	50GK41SA2JA000007	
50GK41SA6HA000019	50GK41SAXJA000028	
50GK41SA8HA000023	50GK41SA1JA000029	
50GK41SA4HA000021	50GK41SA8JA000030	
50GK41SA6HA000022	50GK41SAXJA000031	
50GK41SA2HA000020	50GK41SA1JA000032	
50GK41SAXHA000024		
50GK41SA1HA000025		
50GK41SA3HA000012		
50GK41SA7HA000028		
50GK41SA3HA000026		
50GK41SA5HA000027		
50GK41SA9HA000029		
50GK41SA5HA000030		
50GK41SA4JA000011		
50GK41SA6JA000012		
50GK41SA8JA000013		
50GK41SAXJA000014		
50GK41SA1JA000015		
50GK41SA3JA000016		
50GK41SA5JA000017		
50GK41SA7JA000021		
50GK41SA9JA000022		
50GK41SA0JA000023		

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.



Service Campaign

CC-18-12-01

MODEL: Karma Revero

DATE: February 2018

TITLE: Oil and Filter Change Campaign

Revised Release 2.5.18

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
C161110106200	Filter - Engine Oil	1
C161110109500	OIL ENGINE 5W-30 1QT	5
C161110103800	Drain Plug Washer	1

SHOP SUPPLIES:

DESCRIPTION
N/A

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART:

PART NUMBER	DESCRIPTION
C161110106200	Oil Filter

LABOR CODES:

CODE	DESCRIPTION	TIME	DEFECT CODE
10-10-10-03	Oil and Filter Change Campaign	1.3	10-10-80-98

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

WARRANTY DISPOSITION: This repair is covered under the New Vehicle Limited Warranty, in effect for five (5) years from the in-service date with no mileage limitation.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.