

Reference	SSM73837
Models	Range Rover Velar / L560
Title	Pathfinder release for LTB01182 - Heated seats deactivating during use.
Category	Body
Last modified	29-Mar-2018 00:00:00
Symptom	101000 Seating
Content	<p><u>Issue:</u> LTB01182 - Heated seats deactivating during use has been published in TOPIx with the incorrect Pathfinder release number (149) shown in step 1 of the diagnostic procedure section of the Bulletin.</p> <p><u>Cause:</u> Delay in Pathfinder release to the timing plan.</p> <p><u>Action:</u> Please ensure Pathfinder release 150 or later - due for release on 29th March 2018 is used to fix the Customer reported symptoms that are detailed in LTB01182. * Version 2 of LTB01182 will be published promptly to TOPIx after Pathfinder 150 has been released.</p> <p>Thank you for your assistance in this matter.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>