

## Rubbing or Rattling from the Head Up Display (HUD) Area?

### AFFECTED VEHICLES

Year	Model	Trim
2018	Accord	Touring

Are you hearing a rubbing or rattling from the HUD area? We're aware of this issue and have it under investigation.

So far, we know this noise is coming from contact between the HUD unit and its cover. Some dealers have also reported successfully getting rid of it by applying EPT foam between the unit and the cover.

Until we come up with a solution, we suggest trying the EPT foam fix.