

RR Sport
16MY 3.0L
Diesel

Customer may
experience a CEL
on the instrument
cluster

DTC P2002-00 may be stored in the PCM for "Particulate Filter Efficiency Below Threshold Bank 1". SSM 73738 has been released requesting that if parts need to be replaced, that the Diesel Particulate Filter, Particulate Matter Sensor & Differential Pressure Sensor should be replaced together and an EPQR submitted with your parts manager information. Engineering is requesting these parts back for further analysis

SSM73738