



Service Bulletin

File in Section: -


Bulletin No.: 18-NA-068

Date: March, 2018

INFORMATION

Subject: Information on Tool Requirement for Transmission Selector Lever Cable Removal

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Spark (VIN C)	2016	2018				Manual (MX2, MFM, Y4M)

Involved Region or Country	North America
Information	 <p style="text-align: right;">4993178</p> <p>When separating the selector lever cable (2) from the ball pin (3), it is recommended that a trim pad removal tool (1) be used to aid in eliminating the possibility of damaging the pin locks.</p>

Parts Information

No parts are required for this repair.

Version	1
Modified	Released March 02, 2018

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION