

Subject: Engineering Information – HVAC Not Functioning as Intended or Smell of Burnt Plastic and/or Smoke

This PI has been revised to end the need for information from the field. Please discard PIE0427.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2012	2012			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.