

Subject: Engineering Information — Roof Panel Joint Finish Molding Loose, Missing or Lifting

This PI has been revised to end the need for information from the field. Please discard PIE0435.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2017	2018			All	All
GMC	Canyon	2017	2018			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 26, 2017 March 12, 2018 — Ended the need for further information from the field.