



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-072

Date: April, 2018

INFORMATION


Subject: Information on Installation of Stage One and Two Rear Wicker Bills on Spoiler

This Bulletin replaces PI1478A. Please discard PI1478A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2015	2019			All	All

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with RPO CFV or CFZ

Information



4180967

During the installation of the rear wicker bills that are fastened on the rear spoiler, some technicians may revert to the use of power tools to tighten the fasteners.



4180946

The use of power tools should not be used due to the fact that this could lead to damage to the fasteners and/or the spoiler.

When installing the wicker bills onto the vehicle, it is recommended to hand start the fasteners before using the correct hand tools to tighten the fasteners to the proper torque specifications.

Damage to the fasteners or the spoiler should not be submitted under warranty as the parts are dealer installed components during the pre-delivery process.

Version	2
Modified	April 20, 2018 – Added the 2019 Model Year.