

> Recreational Vehicle > Walk-In Van
> School Bus > S2
> Shuttle Bus

**Freightliner Custom Chassis
Service Bulletin**

NOTICE

Always use new nyloc nuts when installing the engine cooling fan on a Borg Warner (Kysor) fan clutch. Failure to do so may lead to a loose or lost fan, and damage to the fan clutch or the vehicle. Using the wrong type of nuts to install the fan can damage the fan clutch by pushing the studs into the clutch housing causing an internal failure.

Warranty

This bulletin is informational only. Warranty does not apply.