



**AUTOMOBILE DIVISION**  
American Honda Motor Co., Inc.  
1919 Torrance Blvd., - P.O. Box 2215  
Torrance, CA 90509-9870

July 2018

RE: 2017 Civic

This notice applies to your vehicle:

Dear

**What is the reason for this notice?**

Our records indicate that a PRODUCT UPDATE has not been completed on this vehicle; refer to the address card for the affected VIN. The 3-way coolant joint was incorrectly manufactured, and may be internally blocked. If the joint is blocked, a technician will not be able to fill the cooling system properly, which may lead to overheating of the engine.

**What will Honda do?**

Honda will install a new 3-way coolant joint. Contact any authorized Honda dealer for an appointment to have your vehicle repaired **free of charge**.

**If you have questions**

If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda Customer Support & Campaign Center at 1-888-234-2138. You may also find this information at [www.Hondacars.com](http://www.Hondacars.com).

We apologize for any inconvenience this product update may cause you.

Sincerely,

**American Honda Motor Co., Inc.**  
**Honda Automobile Division**

**NOTICE: If this is a leased vehicle, please forward this notice to the lessee.**

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #17-020

KE7