

SSM  
47405

Some 2018 Fiesta vehicles equipped with rear drum brakes built on 8-Mar-2018 and through and through 06-Jun-2018 may exhibit a soft brake pedal feel and/or long brake pedal travel. Replace both front brake caliper. Refer to the Workshop Manual (WSM) Section, 206-06. For claiming, use causal part 2B121 and applicable labor operations in Section 02 of the Service Labor Time Standards (SLTS) Manual.