


## Millimeter Wave Radar Won't Align; DTC P2583-76 Won't Clear

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2017-18	CR-V	EX, EX-L, Touring	ALL
2018	Accord	ALL	ALL
2018	Accord Hybrid	ALL	ALL
2019	Insight	ALL	ALL
2017-18	Civic	With Honda Sensing	ALL

If you're having trouble aligning the front millimeter wave radar, or if DTC P2583-76 is present and does not clear after re-aiming, inspect the radar mounting clips and bracket.

Check that the mounting bracket is not bent or out of shape. Check if the radar unit for play by trying to twist it. If there is play, remove the radar unit and check each mounting clip for damage. Replace all clips that have damage or missing tabs.



These items should be checked first before replacement of the radar unit. If you are still having issues after following this, then replace the radar unit.