

Technical Service Bulletin

46 Rear caliper "S" badge - S4, S5, S5 SB, and S5 Cab

46 18 91 2050535/2 May 24, 2018. Supersedes Technical Service Bulletin Group 46 number 18-84 dated February 22, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S4, S5, S5 Sportback, and S5 Cabriolet	2017 - 2018	All	S brake system

Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised header data (Updated model code) Revised <i>Service</i> (Updated date)		
1	02/22/2018	Initial publication		

Customer states:

• Rear brake calipers missing "S" badge.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Vehicles assembled after CW 22/2017 do not have the "S" logo badge in the rear calipers.


See below examples of old (Figure 1) and new rear calipers (Figure 2):

© 2018 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin






Figure 2. New concept.

Note: Caliper retrofit to the old concept is not allowed and will be debited.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2050535) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2018 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.