



Technical Information Bulletin

56-002



Section

PTO - 56

Subject

T680/T880 PTO Incompatibility With PACCAR and Eaton Endurant Transmissions

Release Date

8/28/2018

Condition

PTOs in certain T680/T880 chassis equipped with PACCAR or an Eaton Endurant Transmission may not contain the wiring required to activate the PTO accessory.

Chassis Affected

64 (64 U.S. and 0 Canada) T680 and T880 chassis built from 02/12/2018 through 06/01/2018 with a PACCAR or Eaton Endurant Transmission and a Chelsea/customer installed PTO.

Action

Campaign Interim Notification

Review the attached chassis list to determine if the chassis you are working with is on the list.

This bulletin will be updated after parts become available.

Attachments



Authored by: GH

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).