

[Next Unread Message](#)

**View Message**

<b>Sent on</b>	09	17	2018	<b>Expires on</b>	09	28	2018
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Visit: 2018 RDX Front Brake Noise						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
 From: Technical Research & Support Group  
 RE: Request for Visit: 2018 RDX Front Brake Noise

**This message is solely directed to Acura dealership personnel; please handle accordingly.  
 Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

**Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2018 RDXs with a client complaint of the front brake noise when applying the brake lightly. The noise can be described as squeak or squeal. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. For 2WD, VIN must be between 5J8TB3...JL002349 & 5J8TB3...JL016078.
2. For AWD, VIN must be between 5J8TB4...JL006168 & 5J8TB4...JL028718.
3. No previous repair to the front brakes.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.