

Reference	SSM74023
Models	F-TYPE / X152 XF / X250 XF / X260 XJ / X351
Title	AJ126 V6 Engine Coolant leak from thermostat housing
Category	Engine
Last modified	30-Aug-2018 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p><u>Issue:</u> The customer reports a coolant leak from the engine compartment which is found to originate from the thermostat housing seam.</p> <p><u>Cause:</u> Multiple process improvements have been implemented at the supplier to mitigate the likelihood of this complaint.</p> <p><u>Action:</u> It is possible the thermostat may suffer consequential damage during a severe overheat event. Investigate and repair any other possible causes of an overheat condition that may exist on the vehicle. Should the VIN reported fall beyond the assured VINs in the applicability table of this document, please raise an EPQR and include pictures of the leak.</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>