

15 & 16MY F-TYPE, XF, XJ, RR, RRS, LR4 equipped with AJ126	A customer may complain of a coolant leak from the vehicle.	Diagnosis finds a coolant leak from the seam of the thermostat housing. Replace parts that are required for repair of the vehicle and hold original parts. Raise an EPQR including pictures of the leak and a list of any other cooling system repairs that were made at this time.	Under Investigation
---	--	--	----------------------------