

1 05 01-18



Service Information Bulletin

SUBJECT	DATE
Aftertreatment Control Module (ACM)	May 2018


Additions, Revisions, or Updates

Publication Number / Title	Platform	Section Title	Change
DDC-SVC-MAN-0190	DD HD	Inspection of the Aftertreatment Control Module	New GHG17 HD section.
		Inspection of the Aftertreatment Control Module	
DDC-SVC-MAN-0083		Inspection of the Aftertreatment Control Module	New EPA07/10/GHG14 section.
DDC-SVC-MAN-0194	DD MD	Inspection of the Aftertreatment Control Module	Updated GHG17 MD section.
DDC-SVC-MAN-0198		Inspection of the Aftertreatment Control Module	
DDC-SVC-MAN-0201		Inspection of the Aftertreatment Control Module	



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

2 Inspection of the Aftertreatment Control Module



d140795

Inspect as follows:

1. Inspect the 21-pin (1) and 120-pin (3) connectors on the Aftertreatment Control Module (ACM) for signs of moisture or water intrusion. If moisture or water intrusion is found, the associated harness should also be replaced.
2. Inspect the 21-pin (1) and 120-pin (3) connectors on the ACM for damaged or bent pins. Repair as necessary.
3. Ensure there is no physical damage to the ACM 21-pin (1) or 120-pin (3) or connector bodies. Replace the ACM as necessary.
4. Inspect the eight ACM isolators (4) for damage. Replace as necessary.