

Range Rover
Velar (Dynamic
only)

False activation of
the front PDC.

Last month we spoke of the ongoing investigation into root cause of this issue on Velar fitted with Dynamic bumpers only. New software has been developed to resolve the false activation. ETA for the updated software to the Park Aid Module (PAM) is the end of August 2018. A publication will be released when the software is available.

TBD