



Bulletin No.: PIC5985C

Published date: N/A

Preliminary Information

PIC5985C Adding NPP Performance Exhaust

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2014 - 2019	All	All	All	All

Supersession Statement

This PI was superseded to update Model Years. Please discard all copies of PIC5985B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A dealer or customer may inquire if RPO NPP (Dual Mode Performance Exhaust System) can be added to a Stingray that was produced without the option.

Recommendations / Instructions

Do NOT attempt to add RPO NPP (Dual Mode Performance Exhaust System) to a car that was not manufactured with it. General Motors does not support the software changes that are required.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

