



To All Lamborghini Dealers and Licensed Service Point
Service Managers
From Customer Service Department
Object Engine oil check Huracàn MY 2018
Group TPI LB62X.01.18
Date 08 March 2018
Pages : 2

Object: Engine oil level too high
Huracàn STD e PERFORMANTE MY18

Model/VIN Range 2018

Information to the field

As a result of continuous product monitoring, Lamborghini Spa has detected that in some cases a pop up message stating reduce oil level together with a yellow oil warning light may appear on the instrument cluster.

Field solution

For these cases Lamborghini is kindly requesting:

1- For cars in PDI check:

carefully check the engine oil level as per described procedure in the workshop manual. And be sure that oil level does not exceed the middle of "Do not fill area" (Fig.2, callout 5).

2- In case of Customer complain:

pop up of "please reduce oil level" (Fig. 1), it is necessary for the dealer to undertake the below listed procedure.



Fig. 1 Oil level too high

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



Preliminary operations:

- Open a technical support quick claim with component code 1150103 and problem code 80 which corresponds to the “improper level”
- Carefully follow the given procedure to determine the engine’s oil level, which can be found of the Huracàn Repair Manual 01 Engine/15 Oil circuit/Oil circuit/Check.
- Provide a picture of the dipstick to attach in the Q.C. (Fig. 2)
- Reduce engine oil by 500 ml from the oil reservoir, regardless oil level is correct by previous check
- Drive the car, if possible, on a flat road for about 10 km keeping the engine speed below 4000 rpm for the entire trip




Fig. 2 Engine oil check

For any further information do not hesitate to contact your Area Manager or service.department@lamborghini.com.

Regards,

Lamborghini Technical Support

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.