

On-car analysis list from August 15th, 2018
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	New Tiguan (LWB)	18	All	All	MIL-on P0441	MIL-on P0441 in the ECM (ONLY vehicles located in Florida, Alabama, Georgia, South Carolina, Mississippi)
	Golf, GTI, SportWagen, Jetta, Beetle, Beetle Convertible, Passat, Tiguan LWB	16-18	1.8T & 2.0T (CPPA,CPLA,CPRA,CPKA,CXBA, CXBB,CXCA,CXCB,DGUA)	All	Oil Level Thermal Sensor	Yellow oil warning light on with any of the following faults P0196 P0198 B104129 B104135 (Warning light must be solid not flashing) (untouched vehicles)
	Jetta	19	All	All	Fuel Line Noise	Customer states fuel line rattle noise (untouched vehicles)
	Golf R	17	All	All	MIL-on P0300-P0304	MIL-on with P0300-P0304 in the ECM with software level 0003 (TSB 01-18-02, 2050261 must have previously been performed) (untouched vehicles)
	ATLAS	18	3.6L (CDVC)	All	Coolant Leak	Coolant leak at the coolant pump (leak must be from mechanical coolant pump) (untouched vehicles)
Body	Golf, GTI, SportWagen	17-18	All	All	Side Mirror Glass Cracked	Side mirror glass cracked (untouched vehicles)
	Tiguan (LWB)	18	All	All	Sunshade Binding	Customer states the sunshade is binding (untouched vehicles)
	ATLAS	18	All	All	Rear Seat	Customer states 60/40 split center seat rattles (untouched vehicles)
	Tiguan (LWB)	18	All	All	Wind Noise	Wind noise from front door window seal area (untouched vehicles) (ONLY front door window/seal noise)
	ATLAS	18	All	All	Sunroof Water Leak	Water leaks from the sunroof/overhead light console area
Chassis	GTI	19	All	All	Damaged Strut Boots	Damaged strut boots at PDI (must be at PDI) (untouched vehicles)
	GTI, SportWagen	17-18	All	Standard	Clutch Pedal Noise	Customer states clutch pedal makes noise during operation (untouched vehicles) (ONLY VINs after HM068470 (GTI)) (ONLY VINs after HM534795 (SportWagen))
Electrical	Passat	17-18	All	All	Key Inoperative	Customer states remote key inoperative (Cars with Kessy system ONLY) (MUST be under 12 month, 12,000 miles)
	Atlas	18	All	All	Park Distance Control	Customer states park distance control too sensitive
	Passat	17-18	All	All	Rear Speaker Distortion	Customer states the rear speaker is distorted (untouched vehicles)