



Technical Tip

Topic	87-18-02TT - Front Air Conditioning Vent Temperature not Cold
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	October 19, 2018

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Front Air Conditioning Vent Temperature not Cold

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2018	All	All	All	All

Technical Background

Customer complains that the front A/C vent temperature is not as cold as the rear A/C vent temperature.

Service

- Connect a scan tool.
- Navigate to control module OBD, AW08, coding.

If index line 7, byte\$7 is coded to 14 (hex value):

- Change the coding to 1C.

Check the A/C operation by monitoring the front evaporator output temp in MVB, should read 3°C or less.

Additional Information

Revision History

Revision Number	Released Date	Reason For Update
2052727/1	10/19/18	Original publication.

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.