

## GPOP - Issue Review System

**Part Number:** 68073732A\$

**Part Description:** Door Speaker

**Issue Description:** Many speakers on VFs built 1/1/14-9/29/14 were misassembled. If the customer has a VF built during this time frame and states either of the door speakers are inoperative, crackle, or sound distorted, please replace BOTH door speakers to ensure the customer will not have to return again due to the same failure.~

~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.