

GPOP - Issue Review System

Part Number: 68240156A\$, 68240157A\$

Part Description: Radio Frequency Module RF_HUB

Issue Description: If customer complain is "Key not detected" show in the cluster and/or car will not start, before replacing RF_HUB please contact Majdi Yaqub at cell (248) 763-5747. If no response in 15 minutes, proceed with repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.