

Technical Service Bulletin

91 MIB2 with ignition on, the screen does not retract with the "Screen On/Off" button

91 18 09 2052238/1 August 24, 2018.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, Q7	2018 - 2019	All	MIB2

Condition

The customer states that when the ignition is on the screen does not retract with the button "Screen On/Off" or with the MMI on/off button.



Figure 1. Screen On/Off button.

Technical Background

Due to recent changes in regulation, the rear view camera has to be available within a certain timespan after the vehicle is put into reverse.

In order to facilitate this regulation, the screen cannot be lowered any more by the customer while the ignition is turned on.

Production Solution

Not applicable.

Service

The vehicle is functioning correctly.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Required Parts and Tools

A part replacement is not authorized.



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2052238) are subject to change and/or removal. . Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2018 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.