

**On-car analysis list from July 5th, 2018**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	ATLAS	18	3.6L (CDVC)	All	Engine Oil Leak	Customer states engine oil leak <b>(leak must be from oil pan, front crank sealing flange or vacuum pump)</b> <b>(untouched vehicles)</b>
	New Tiguan (LWB)	18	All	All	MIL-on P0441	MIL-on P0441 in the ECM <b>(ONLY vehicles located in Florida, Alabama, Georgia, South Carolina, Mississippi)</b>
	ATLAS	18	3.6L (CDVC)	All	MIL-on P0030 P0050 P0051 P0133 P0151 P0152	MIL-on with any of the following P0030 P0050 P0051 P0133 P0151 P0152 in the ECM <b>(untouched vehicles)</b>
	ATLAS	18	3.6L (CDVC)	All	MIL-on P054A P0014 P0017 P052A P053A P0010 P0011 P000B P0016	MIL-on with any of the following P054A P0014 P0017 P052A P053A P0010 P0011 P000B P0016 in the ECM <b>(untouched vehicles)</b>
	ATLAS	18	3.6L (CDVC)	All	Coolant Leak	Coolant light on or coolant odor with coolant leak <b>(leak must be from coolant pump)</b> <b>(untouched vehicles)</b>
<b>Body</b>	Golf, GTI, SportWagen	17-18	All	All	Side Mirror Glass Cracked	Side mirror glass cracked <b>(untouched vehicles)</b>
	Tiguan (LWB)	18	All	All	Sunshade Binding	Customer states the sunshade is binding <b>(untouched vehicles)</b>
	ATLAS	18	All	All	Fuel Door Actuator Faulty	Fuel door won't open or fuel door won't unlock.
	ATLAS	18	All	All	Sunroof Water Leak	Water leaks from the sunroof/overhead light console area
<b>Chassis</b>	GTI	19	All	All	Damaged Strut Boots	Damaged strut boots at PDI <b>(must be at PDI)</b> <b>(untouched vehicles)</b>
	GTI, SportWagen	17-18	All	Standard	Clutch Pedal Noise	Customer states clutch pedal makes noise during operation <b>(untouched vehicles)</b> <b>(ONLY VINs after HM068470 (GTI))</b> <b>(ONLY VINs after HM534795 (SportWagen))</b>
<b>Electrical</b>	Passat	17-18	All	All	Key Inoperative	Customer states remote key inoperative <b>(Cars with Kessy system ONLY)</b> <b>(MUST be under 12 month, 12,000 miles)</b>
	Passat	17-18	All	All	Rear Speaker Distortion	Customer states the rear speaker is distorted <b>(untouched vehicles)</b>