

# SS 1033446 Driveline Support Bearing - Meritor Driveline

---

## **SS 1033446 Driveline Support Bearing - Meritor Driveline**

### **Applicable Vehicles**

All Freightliner and Western Star with Meritor driveline, 2 or more drivelines, Model 176MXL, 18MXL, RPL25, 16MXL or 17MXL

### **Symptoms**

Vehicle continues to exhibit 1st order driveline vibration (confirmed with an EVA tool) after the drivelines have been system balanced (2 or more shafts at a time).

### **Issue**

Some vehicles with specific Meritor drivelines may benefit from a softer durometer center bearing support. Vehicle will continue to have a 1<sup>st</sup> order driveline vibration after the driveline assembly was rebalanced.

### **Solution**

Replace the original isolator with the softer version listed.

Driveline Model	Original Hard	Replacement SOFT
176MXL	TDA HCB205	TDA HCB214
18MXL	TDA HCB205	TDA HCB214
RPL25	TDA HCB205	TDA HCB214
16MXL	TDA CCB206	TDA CCB213
17MXL	TDA CCB206	TDA CCB213